



RZ - 5261-3 Polyamine Cured Epoxy Flexible Flooring

Product Description

RZ-5261-3 is a two component, polyamine cured, solvent free epoxy flexible floor coating.

Recommended Use

As a suitable floor coating on concrete or steel industrial floors subjected to continuous mechanical wear and where chemical, solvents resistance and flexibility is required.

Outstanding Characteristics

- Excellent mechanical strength.
- High oil resistance.
- High chemical resistance against weak acids and alkalis.
- Easy application.
- Very good flexibility more than solvent free epoxy polyamine flooring

Surface Preparation

The surface must be clean and dry. All dirt, grease, mill-scales and any other foreign materials should be removed.

Characteristics

Foot traffic at 25°C 2- 3 days Vehicle traffic at 25°C 7days

Technical Data

Finish High gloss

Color White, light color

Volume Solids 98±2%

Specific Gravity $1.6 \pm 0.05 \text{ gr/cm}^3$

Dry Film Thickness 1000-3000 microns

Theoretical Coverage 0.95-0.3 m²/lit

 $0.6-0.2 \text{ m}^2/\text{kg}$

Touch dry 6 hrs at 25 °C

Fully cured 7 days at 25 °C

Thermal Resistance Up to 120 °C

Shelf life 12 months at 25 °C

Application Details

Application method knife, Trowel

Ambient temperature 10-45 °C

Mixing ratio Base / Hardener 7 / 1 by weight

Pot life 1hrs at 25°C

Product Data/ RZ-5261-3/ Page 2 of 2

Application Procedure of RZ-5261-3

- 1. Flush all equipment with recommended cleaner before use.
- 2.Stir pigmented resin to an even consistency with a power mixer.
- 3.Add cure to pigmented resin ,and continue stirring for 5 minutes .

Note: Since the pot life is limited and shortened by high temperatures; do not mix more material than will be used in 1hour at 25°C.

4.DO NOT THIN FOR ANY REASON.

- 5.Stir during application to maintain uniformity of material. Apply a wet coat by parallel passes with putty knife or trowel. Overlap each pass 50% to avoid bare areas, pinholes or holidays.
- 6. Clean all equipment with recommended cleaner immediately after use.

Environmental Conditions

Surface temperature must be at least 3° C above dew point. Relative humidity during application should be less than 80%. Do not apply coatings under reverse environmental conditions. Each coat shall be air dried a minimum of 12 hours at 68°F (25° C). Theses coating shall not be applied at temperatures below 10° C.

Safety

This product is flammable. Keep away from heat and open flame. Keep container closed. Avoid prolonged and repeated contact with skin.

Since improper use and handling can be hazardous to health and cause fire or explosion, safety precautions included with application instructions must be observed during all storage, handling, use and drying periods.

If used in confined areas:

- circulate adequate fresh air continuously during application and drying.
- Use fresh air masks and explosion proof equipment
- Prohibit all flames, sparks, welding and smoking
- Take precautionary measures against static discharges

Keep away from food products.

Storage conditions

Store in cool dry conditions, away from sources of heat and naked flames, in the original, unopened packs. If stored at high temperature, the shelf life may be reduced.

Disclaimers

The information in this data sheet is given to the best of our knowledge based on laboratory testing and practical experience.

However we reserve the right to change the given data without notice.

Any recommendation relating to the use of the products is based on data believed to be reliable. It is buyer to satisfy itself of the suitability of the product for its own particular use.

As the product is often used under conditions beyond our control, we cannot guarantee anything but the quality of the product itself.

RANGIN ZEREH

High Performance Protective Coatings

No.15- 15th St. Bokharest Ave. Tehran/ Iran Tel: +98 21 88723676 Fax: +98 21 88716358 http://www.Ranginzereh.com Email: info@Ranginzereh.com